ISTA/P

Final report

Session name:	E70_L662139
Duration:	01:44:43
Measures plan implementation successful:	Cancellation by user
Concluding work, notes:	present (see below)
Change vehicle order:	No

Header data

Date:	10/8/2017	Time:	7:31:26 AM	ISTA/F	o version:	3.60.0.600
Model series:	E70	Type/descri	ption:	ZW03 / E70 M57	SD30 LHD U	S
Odometer:			Vehi	cle ID number:	5UXZW00	C50BL662139
Integration level (plant):	Integration	evel (old):	Integra	ation level (ne	ew):
E070-11-03-511		E070-12-03	-503	E070-1	16-11-500	
Time criterion:	0411	Paint code:	0475	Uphols	stery code:	LUSW
E words:		A090				
K words:		AHMU				
SA numbers:		441, 456, 46 5DK, 609, 6	4, 488, 494, 496, 4	AB, 4NA, 4NB, 50 697, 6AA, 6AB, 6F	2, 508, 521,	30, 3AH, 402, 417, 430, 431, 522, 524, 544, 548, 563, 575, , 760, 761, 775, 823, 838, 853,

ISTA/P

Programmings sequential OBD (K line, DCAN)

*fixed sorting according to execution sequence

-	•						
Control module	Action	Result / fault code	Status	Туре	Hardware index	Part number prog. ECU old	Part number prog. ECU new
CAS	Program P	Successful	\checkmark	Sys	C4	9278746	9389116
JBE	Program P	Successful	\checkmark	Sys	00	9277250	9292707
DSC	Program P	Successful	\checkmark	Sys	09	6854704	6864696
CON	Program P	Successful	\checkmark	Sys	19	9249439	9334611
SMFA	Program P	Successful	\checkmark	Sys	03	9221863	9264976
SMBF	Program P	Successful	\checkmark	Sys	03	9221863	9264976
FRM	Program P	Successful	\checkmark	Sys	08	9287251	6801293
CID	Program P	Successful	×	Sys	A17	9232896	9289580
IHKA	Program P	Successful	¥	Sys	07	9279654	9310449
TRSVC	Program P	Successful	¥	Sys	03	9277953	9291387

Encodings

*fixed sorting according to execution sequence

Control module	Action	Result / fault code	Status	Туре	Hardware index	Part number prog. ECU old	Part number prog. ECU new
DSC	Code C	Successful	\checkmark	Sys	09	6854704	6864696
CAS	Code C	Successful	\checkmark	Sys	C4	9278746	9389116
FRM	Code C	Successful	\checkmark	Sys	08	9287251	6801293
JBE	Code C	Successful	\checkmark	Sys	00	9277250	9292707
IHKA	Code C	Successful	\checkmark	Sys	07	9279654	9310449
SMFA	Code C	Successful	\checkmark	Sys	03	9221863	9264976
SMBF	Code C	Successful	\checkmark	Sys	03	9221863	9264976
CON	Code C	Successful	\checkmark	Sys	19	9249439	9334611
TRSVC	Code C	Global.VehicleCo mmunication.CoA Pl.1000 - (CoAPI) - General fault	×	Sys	03	9277953	9291387

Initializations

Time: 7:31:26 AM

Control module	Action	Result / fault code	Status	Туре
-	Initialisation by terminal change	Failed	x	Sys

Actions, post-programming initialisations

Action	Note	Result	Status	Туре
Save MOST configuration	-	Successful	 Image: A set of the set of the	Sys
Longitudinal acceleration sensor adjustment	-	Successful		Sys
Initialisation, RDC warning	-	Successful		Sys
Adjustment, steering-angle sensor	-	Successful		Sys
Deactivate compressor running-in protection	-	Successful	V	Sys
Teach in all round view camera	-	Successful		Sys
Initialising rear power window regulator	-	Successful		Sys
Initialising front power window regulator	-	Successful	V	Sys
Clear fault code memory	-	Warning	۸	Sys
Date: 10/8/2017			VIN:L66	62139

ISTA/P

Actions, post-programming initialisations

Action	Note	Result	Status	Туре
Read fault code memory	-	Successful	×	Sys

Enabling code action

Control module	Description	Software ID	Action	Result	Status
во	BMW Apps	009C0001	Import activation code	The appropriate enabling code could not be obtained via SWT Online and was not imported manually.	<u>*</u>
во	BMW Apps	009C0001	Activate A	The appropriate enabling code could not be obtained via SWT Online and was not imported manually.	A

Activation code status (before plan execution)

Control module	Description	Application No.	Upgrade index	Status
BO	Voice control	0017	0001	activated
ВО	NAV application software	0019	0001	activated
во	NAV authentication	001B	0001	activated
во	Road Map North America PREMIUM 2017-1	002D	0029	activated

Data recovery

Control module	Action	Result	Status	Туре
во	Save individual data	Warning	٨	Sys
во	Restore individual data	Warning	<u> </u>	Sys

Additional actions

Control module	Action	Result / fault code	Status
-	Update integration level	Successful	~
-	Vehicle order alignment	Successful	×

Concluding work, notes

Number	Activity / note
1.	(Clear fault code memory)
2.	(Initialisation by terminal change)
3.	TRSVC (Code C)